

“9010seriesUp.exe” software history 2.42

For models 9010, 9010F and 9010/xxP series

Here are reported only the last 3 releases, the complete release history is available on request

| Ver. | Date | Applied Modifications |
|------|------------|--|
| 2.42 | 11/04/2019 | <ul style="list-style-type: none"> – To run the upgrade the software Driver_Setup.exe must be in the same directory |
| 2.41 | 10/04/2019 | <ul style="list-style-type: none"> – 9010 series up release 2.41 – 9010F firmware release 1.89 |
| 2.40 | 27/02/2019 | <ul style="list-style-type: none"> – 9010 series up release 2.40 – 9010F firmware release 1.86 |

| 9010 and 9010/xxP Firmware | | |
|----------------------------|------------|--|
| Ver. | Date | Applied Modifications |
| 2.64 | 23/08/2018 | <ul style="list-style-type: none"> – Sweep mode, solved the wrong interpolation when there are one or more factors and too many steps |
| 2.57 | 04/10/2017 | <ul style="list-style-type: none"> – Fixed the bug about the report using the 4 channel click analyzer |
| 2.56 | 12/01/2015 | <ul style="list-style-type: none"> – Minor bugs fixed |

| 9010F Firmware | | |
|----------------|------------|--|
| Ver. | Date | Applied Modifications |
| 1.89 | 03/04/2019 | <ul style="list-style-type: none"> – Improved communication with internal LISN CA0010 – Minor graphic bug correction |
| 1.86 | 19/02/2016 | <ul style="list-style-type: none"> – Reviewed the system of measuring the QP detector with the 9060 – Reviewed the system of measuring the C-AVG for Intermittent Unsteady Disturbance |
| 1.85 | 07/02/2019 | <ul style="list-style-type: none"> – Remote FAN support |