

**L3HARRIS****narda**   
Safety Test Solutions

## “ER8000SeriesUp\_setup.exe” software history 1.05

Ver.	Date	Applied Modifications
1.05	27/08/2021	<ul style="list-style-type: none"> <li>– Setup 1.05</li> <li>– Firmware release 0.52</li> </ul>
1.04	22/07/2021	<ul style="list-style-type: none"> <li>– Setup 1.04</li> <li>– Firmware release 0.48</li> </ul>
1.03	23/06/2021	<ul style="list-style-type: none"> <li>– Setup 1.03</li> <li>– Firmware release 0.43</li> </ul>
1.02	11/06/2021	<ul style="list-style-type: none"> <li>– Setup 1.02</li> <li>– Firmware release 0.42</li> </ul>
1.01	18/05/2021	<ul style="list-style-type: none"> <li>– Setup 1.01</li> <li>– Firmware release 0.39</li> </ul>

ER8000 Firmware		
Ver.	Date	Applied Modifications
0.52	23/07/2021	- In “sweep mode”, fixed bug that prevented the user from sweeping with an arbitrary step.
0.48	22/07/2021	- Improved correction factors
0.43	23/06/2021	- Restored conversion factor functionality
0.42	11/06/2021	- Performance improvement in sweep and analyzer mode
0.39	12/05/2021	- Solved a bug that prevented the creation of the automatic click report, when a single click was detected only on channel 3 and/or 4